

# UNIVERSITY SYNAGOGUE - WEEK AT A GLANCE - 7/30/2008



*Interior: General progress photo - library / ductwork*



*Exterior: Scaffold erection*



*Exterior: Entryway site asphalt removed and surveying underway to lay out the new entry configuration*



*Exterior: Below grade waterproofing complete, back-fill of dirt underway*

**Hot issues:** N/A this week

